

【図1】




EZE O TONO CO.


【図2】




【図3】



【図4】



【図5】



提出日 特願2000-035215


【図6】

	液漏れ		ブースタ失陥	正常
	少量	多量	ノーヘン大幅	正市
$F = F_0(F_0 \le F < F_1)$ $P_{M0} \ge P_{th1}$	0	×	×	0
$F = F_2(F_2 < F)$ $P_{M2} \ge P_{th2}$	X	×	0	0
朴ミング有	0	0	X	×
ポミング時 dPm dt <β (β<0)	0	ı X	×	×.


○:左欄の条件を満たす場合

★:左欄の条件を満たさない場合


【図7】




【図8】



【図9】




【図10】





提出日 特願2000-035215

【図11】





【図12】







(c) 負圧室の圧力








(e)液漏れあり系統




【図13】

ブレーキ操作中サーボ失陥



(a) マスタ液圧変化



【図14】

